Abstract

A first marking 20 and a second marking 30, indicating a connection form, are provided on a covering sheath 11 at a connection position of a first wire 10 serving as a main wire. Therefore, an operation is carried out at a region between the first marking 20 and the second marking 30 of the first wire 10 according to an operation form indicated by the second marking 30. Therefore, the predetermined form of operation can be carried out errorlessly at the predetermined position of the first wire 10 without consulting a manual or the like.

5

10